

Bulletin Number: PS - 7 - 2011

Bulletin Date: July 2011

SERVICE BULLETIN

Subject: Model Series Revision, F0822 and N0622 to B Series

The compressor used in these models has been changed.

The new service parts are:

Model	Electrical	Compressor*	Overload	Relay	Start Cap	Run Cap
N0622, F0822 -1 B	115/60/1	18-8949-21	18-8949-50	18-1903-44	18-1901-65	18-1902-64
N0622, F0822 -32 B	208-230/60/1	18-8949-22	18-8949-51	18-1903-54	18-1901-45	18-1902-30
N0622, F0822 -6 B	230/50/1	18-8949-23	18-8949-52	18-1903-70	18-1901-52	18-1902-65

^{*} Service compressors include starting components and a dryer.

The prior compressors will still be available for replacement in A series models. The two are not interchangeable.