

Bulletin Date: October 2012

SERVICE BULLETIN

Subject: Change to MDT3, 4, 5 and 6 Controller

The controller used on the MDT3, MDT4, MDT5 and MDT6 has been changed.

The change began with MDT6N90A-1J, serial number 12101320011878, manufactured on 10-16-12.


The controller is now manufactured with surface mount technology, which makes the controller appear different. See the photos below. Also changed was the dispense relay. Its rating was increased to 30 amps to reduce possible contact damage. A damaged relay could increase the potential of continuous dispensing.

There are no operational differences between the two, all prior features are continued in the new controller and they are interchangeable.

The service controller, part number 12-2843-21, has also been changed.



Prior Design



Current Design