

SERVICE BULLETIN

Subject: Compressor and Series Change to CU50 and SCC50 Product Family.

Due to a supplier discontinuation, the compressors in the above models have been changed. The compressor changes also affected the EEPROM values on the controller. Prior compressors and controllers are not interchangeable with the new series.

New Model Series	New Compressor Part Number	New Compressor Relay	Overload	Controller Part Number
CU50GA-1C	18-8994-21	18-8994-52	18-8939-51	11-0573-52
CU50PA-1C	18-8994-21	18-8994-52	18-8939-51	11-0573-52
SCCG50MB	18-8994-21	18-8994-52	18-8939-51	11-0573-52
SCCP50MB	18-8994-21	18-8994-52	18-8939-51	11-0573-52

Controller EEPROM changes:

Freeze timer starts at: 3° Fahrenheit was 0° Fahrenheit (Temperature at suction line thermistor)

Default freeze timer: 11 Minutes was 10 Minutes