

---

# SERVICE BULLETIN

---

**Subject: Design Change to Meridian Series Ice Machines.**

Applies to the following models: HID312, HID525 and HID540

**What changed:** The internal ice storage bin cover is now insulated. This is to minimize the risk of condensation forming on the bin cover top in high humidity environments.

**When changed:** The insulated covers were added to all HID units beginning April 2018

**Prior units:** The insulated cover can be added to any of the prior HID units if needed.

**Part numbers:**

Model:	Part Number
HID312	02-4998-01
HID525	02-4998-02
HID540	

