

# SERVICE BULLETIN

---

## Subject: CME810 Float Stem Color Change

The color of part number **02-3777-04** has been changed from light blue to **black**.

The infrared light of the water level sensor must be blocked by the plastic of the float stem to properly signal level of the water to the controller. Light blue has been found to be inconsistent in blocking that light, causing irregular cube size and water fills.

There is an existing black float stem, used on SCE275. It is part number 02-3383-03. They must not be mixed up. The part numbers are molded onto the side of the part and they are physically different.

- CME810 float stem has a loop top.
- SCE275 float stem has a flat top.