

# SERVICE BULLETIN

## Subject: Design Change to Water Distributor Mounting Bracket

Part numbers 02-4205-01 and 02-4205-02, used in all Prodigy cubers, have been changed.

The changes are to shorten the guide slot that the water distributor rides in and to add a guide bar to the back.

The original slot length had the potential to allow the material by the slot to sag. If the part sags far enough it could be in the water path and affect how water flows by the ice thickness sensor. The shorter slot eliminates that potential.

The guide bar provides alignment for the water distributor when replacing it after maintenance.

