

SERVICE BULLETIN

Subject: Service Part Number Change

The part number for the service controller for all Prodigy cubers has been changed.

The old number was 11-0550-25, the **new part number is 11-0550-26**. All features remain the same and it is completely interchangeable with all prior Prodigy controllers.