


Bulletin Number: PS - 5 - 2007 Bulletin Date: August 2007

SERVICE BULLETIN

Subject: New TXV Insulation Cover

The cover used over thermostatic expansion valves has been changed. The new cover is self-adhesive and does not require cable ties to hold it in place. The joint between the halves is very tight, improving insulation ability. Replacement of a TXV equipped with the new cover requires a replacement cover. Current production service TXVs will be changed to include the new covers. Alco valves use cover part number **02-4406-01**, Danfoss valves use cover part number **02-4405-01**.



Usage Reference

Current production models using Danfoss TXVs include: CME306, CME456, CME506, C0830, C1030, C1448, C1848, C2148, EH222, EH430 All others use Alco.



Bulletin Number: PS - 6 - 2007 Bulletin Date: August 2007

SERVICE BULLETIN

Subject: SCE275 Air Cooled High Pressure Cut Out

A high pressure cut out switch has been added to the air cooled models of the SCE275 ice machine. The part number of the cut out switch is 11-0501-05. It is an auto-reset type switch. It cuts out at 500 PSIG and cuts in a 390 PSIG. When the switch opens, it stops the compressor, but the controller continues to time out the cycle it is in, so a high pressure situation could be a cause for a maximum freeze cycle.

Production began with SCE275A-1H, serial number 07081320015007.