

---

# SERVICE BULLETIN

---

**Subject:** Quick Connects

The new “E” revision Remote Cooled Ice Makers, Remote Condensers and Line Sets will no longer connect with quick connects. Prior Units, Condensers and Line Sets are compatible with the new E-series. During the transition from quick connects to braze connections, the Ice Maker, Condenser and Line Sets may or may not have quick connects. If the Condenser and/or Ice Maker has quick connects and the Line Sets does not then the KTE4 kit is required.

It is important to follow the proper installation procedure found in the user manual. This applies to both quick connect and field braze connections.

Item Number	Description
KTE4	Tube End Kit, includes two 1/2 and two 3/8 Quick Connect Fittings with Stubs
BRTE10	10’ Line Set, Brazing will be required
BRTE25	25’ Line Set, Brazing will be required
BRTE40	40’ Line Set, Brazing will be required
BRTE75	75’ Line Set, Brazing will be required